

# 7120 CLEANER



## DESCRIPTION:

Weld-All 7120™ Pipe Cleaner is a special blend of solvents formulated to clean PVC, CPVC, ABS and Styrene Pipes & Fittings, all schedules and all diameters, prior to applying cement. This Pipe Cleaner will effectively remove oils, dirt, grease and other foreign matter from the surface of pipe and inside of fitting. It is very important that the surface of pipe and inside of fitting is clean for a strong leak proof joint. This product is made in the U.S.A

## APPLICATION:

Weld-All 7120™ Pipe Cleaner may be used on PVC, CPVC, ABS and Styrene. Use applicator supplied with can or suitable applicator ½ the size of pipe being joined.

Application temperature:  
-10 degree F to 120 degree F


Storage temperature:  
-10 degree F to 110 degree F

## PROPERTIES AND SPECIFICATIONS:

Color	Clear
Appearance	Liquid
Shelf Life	3 years

## AVAILABILITY:

SIZE	PART NO	UNITS/CARTON	
4 FLUID OZ / 120 ML	712004	24	CAN WITH BRUSH IN CAP
8 FLUID OZ / 237 ML	712008	24	CAN WITH BRUSH IN CAP
16 FLUID OZ / 487 ML	712016	12	CAN WITH BRUSH IN CAP
32 FLUID OZ / 947 ML	712032	12	CAN WITH BRUSH IN CAP



7120

# 7120 CLEANER



## DIRECTION FOR USE:

---

Keep container closed when not in use.

1. Apply Cleaner with applicator supplied with can or suitable applicator.
2. Wipe off with clean dry cloth.
3. Apply cement according to instruction on cement can.
4. Cement should not be applied when Cleaner is wet.

## PRECAUTIONS:

---

**EXTREMELY FLAMMABLE LIQUID, VAPOR MAY IRRITATE EYE OR SKIN, MAY CAUSE FLASH FIRE, MAY BE HARMFUL OR FATAL IF SWALLOWED. DO NOT USE NEAR HEAT, SPARKS AND FLAMES. KEEP OUT OF REACH OF CHILDREN.**

Ensure adequate ventilation to avoid vapor build up which may cause flash fire. Vapor build up may also cause dizziness, headache or eye watering. If symptoms are experienced use respiratory protection or leave area and provide more fresh air. Avoid contact with eyes, skin and clothing. Do not smoke and wear protective equipment while using

## FIRST-AID:

---

- Inhalation:** If breathing is difficult vacate to fresh air. If breathing problems persist seek immediate medical attention.
- Eye Contact:** Flush eyes thoroughly with water for 15 minutes. Seek immediate medical attention.
- Ingestion:** If swallowed, give 1-2 glasses of water immediately, call physician, hospital or poison control center immediately. **DO NOT INDUCE VOMITING**
- Spill:** Remove all source of ignition and ventilate area. Soak up spill with absorbent material. Dispose of absorbent material in accordance with regulations. Personnel cleaning the spill should wear appropriate protective equipment.

**WARRANTY:** Weld-All™ warrants that all of its new products shall be of good quality and free from defects. If any product becomes defective Weld-All™ will replace defective product at no charge. **WARRANTY IS LIMITED TO REPLACEMENT OF DEFECTIVE MERCHANDISE**